


Drawing Name: Z:\1146.01 - Britain Woods\EAF & EIS Figures\1146.01 - EIS Figures.dwg Date Printed: Feb. 10, 2026, 10:03am

Test Pit #	Cut Depth	Rock	Water
1	4'	No Rock	No Water
2	6'	No Rock	No Water
3	8'	No Rock	No Water
4	10'	No Rock	No Water
5	4'	No Rock	No Water
6	4'	No Rock	No Water
7	6'	No Rock	No Water
8	5'	No Rock	No Water
9	8'	No Rock	No Water
10	4'	No Rock	No Water
11	10'	No Rock	Mottling @ 6'
12	9'	No Rock	Mottling @ 4' & 9'
13	11'	Rock @ 7.5'	Mottling @ 4'
14	11'	Rock @ 8'	No Water
15	17'	Rock @ 14'	No Water
16	12'	No Rock	No Water
17	7'	Rock @ 2'	No Water
18	6'	No Rock	No Water
19	16'	No Rock	No Water
20	25'	Rock @ 13'	No Water
21	6'	No Rock	No Water
22	5'	No Rock	Mottling @ 3'
23	9'	Rock @ 6'	No Water
24	23'	No Rock	No Water
25	10'	Rock @ 5'	No Water

TEST PIT DATA	BRITAIN WOODS NYS ROUTE 207 TOWN/CITY OF NEWBURGH ORANGE COUNTY, NEW YORK	DATE: 02/10/26	JOB # 1146.01	 ENGINEERING & SURVEYING PROPERTIES <small>Achieving Successful Results with Innovative Designs</small>	MONTGOMERY OFFICE 71 CLINTON STREET MONTGOMERY, NY 12549 Ph: (845) 457-7727 WWW.EP-PC.COM
		SCALE: NTS	SHEET # 3.1D		